



Prosper Fire Rescue

Fire Marshal's Office

PO Box 307

911 Safety Way

Prosper, Texas 75078

Phone (972) 346-9469 Fax (972) 347-3010 www.prosperfire.com

Top Reasons Hood Suppression System Installations Fail Inspections

1. Failing to ensure an approved method is provided that will ensure the appliance is returned to the approved design location – [NFPA 17A-5.6.4](#)



2. Failing to install [IFC-2015 904.12.5.2](#)
3. Failing to ensure safety measures are in place for gas-powered cooking appliances – [Mfg. Requirements](#)



4. “K” Class extinguisher and signage is installed to codes & standards by the licensed contractor – [NFPA 96-10.9.2 & NFPA 10](#)
5. Failure to provide an extinguisher for other hazards in the kitchen area - [NFPA 96-10.9.3 & NFPA 10](#)
6. Failure to pre-test the system with other trades in the presence of the owner or the owner’s representative prior to the final acceptance test with the AHJ
7. Failure to provide As-Built drawings reflecting the actual installation